

Work Order	Description	Date Completed	Equipment Description
DS14782991	Fee 73 replace 2" casing choke	1/13/2014 16:00	WELLHEAD; FEE 73X
DS13440118	FEE 73X PUMPING UNIT REMOVE RECEPTACLE	4/29/2014 14:00	WELL; FEE 73X
DS15008704	Fee 73 repair berm	6/3/2014 16:00	WELL; FEE 73X
DS15068172	RANGELY LEVEL III AUDITS CS27; FEE 73	7/1/2014 17:31	WELL; FEE 73X
DS15450255	JVGJ 2HR FE73 – Check Low Min Load.	12/3/2014 18:12	WELL; FEE 73X
DS15462862	FEE73 ADJ POC/RIG7 ADJ POC	12/10/2014 17:16	PUMPUNIT; FEE 73X
DS15489578	JVGJ 2HR FEE 73 LOW MIN LOAD	12/24/2014 13:36	PUMPUNIT; FEE 73X
DS15497134	FEE 73; THAW/AIRUP, ADJ BELTS	12/31/2014 18:01	PUMPUNIT; FEE 73X
DS15719925	FEE 73; CLEAN MURPHY CONTACTS, BLED OFF WELLHEAD	3/13/2015 14:23	WELL; FEE 73X
DS15772764	JVGJ 2HR fee 73 comm fail; FOUND broke center phase	4/17/2015 16:30	WELL; FEE 73X
DS15777497	FEE73 DISCON 4 MOONLAKE	4/21/2015 18:34	WELL; FEE 73X
DS15954621	Fee73 3/8" check on air system not functioning	8/3/2015 13:01	WELL; FEE 73X
DS15980435	FEE73 FILL TUBING, RESTART	8/26/2015 18:47	PUMPUNIT; FEE 73X
DS16010065	Fee 73; top oil with Prime	9/22/2015 18:49	PUMPUNIT; FEE 73X
DS16127837	FEE 73; LOAD TUBING W/PRIME, STARTUP	12/1/2015 17:45	PUMPUNIT; FEE 73X
DS16223955	FEE 73 H.T.	12/9/2015 16:06	PUMPUNIT; FEE 73X
DS16230760	Fee 73 heat trace not working; loto for Chuck	12/9/2015 16:23	PUMPUNIT; FEE 73X
DS16717181	FEE73 PROG ERROR; REINSTALLED PARAMETERS, REPL POC BATT	3/17/2016 17:36	PUMPUNIT; FEE 73X
DS16786540	FEE 73; REALIGN POS SWT	5/4/2016 19:43	WELL; FEE 73X
DS16807763	FEE 73; REPL POS SWT	5/10/2016 18:38	PUMPUNIT; FEE 73X
DS16963395	FEE73 - WELDER TO CUT TIP OF HORSES HEAD	7/20/2016 9:02	WELL; FEE 73X
DS17035071	FEE 73; F.L. LEAK BETWEEN WELL AND HEADER (SEE COMMENTS)	8/22/2016 7:00	LINE; PRODUCTION, FLOW FEE 73X
DS17112309	Fee 73 repair berm where road crosses	9/30/2016 14:07	WELL; FEE 73X
DS17118811	Fee 73 alarms have cleared during the night according to LOWIS	10/11/2016 15:47	WELL; FEE 73X