



Photo#1: There is no evidence of the AL Well on this Active Location.

December 23, 2016

Inspection Photos:Encana AL KRK: API# 045-10648



Photo#2: There is no evidence of the AL Well on this Active Location with Seven PR Wells.

Inspection Photos:Encana AL KRK: API# 045-10648

December 23, 2016