



Photo#1: There is no evidence of the AL Well on this Active Location.



Photo#2: There is no evidence of the AL Well on this Active Location with Four PR Wells.

Inspection Photos: Encana AL KRK API#045-08926

December 23, 2016