



Photo#1: There is no evidence of the AL Well on this Active Location.



Photo#2: There is no evidence of the AL Well on this Active Location with Three PR Wells.

Inspection Photos: Encana AL Pitman API#045-07951

December 23, 2016