

TEP Rocky Mountain LLC  
RU 513-7  
Rulison Field  
Section 7T 7S-R93W

Formation Tops  
(Measured Depths)

Conductor 26" Hole 18" casing/liner 63' W/ 15.75 Sks

AFL 0'

9-5/8" 32.3 ppf Csg. Set @1155.7'  
In 13-1/2" Hole W/305Sks.

Top Of Cement 3974

"G" Sand @ 3337

Mesaverde @ 5698

Cameo @ 8380

Tubing not set

PBTD @ 9390

Float Collar @ 9414

TMD @ 9452

TVD @ 9413.7

Est.Top Perf @ 7230

Top Of Gas @ 7330

4-1/2", 11.6 ppf. Csg. Set @9,9442' W/1030SKS