



Photo#1: View over GPS Position of AL Well (indicated by Arrow). There is no evidence of the AL Well on this Active Location.



Photo#2: There is no evidence of the AL Well on this Active Location with Five PR Wells.

Inspection Photos: Encana BJM AL API# 045-08219

January 10, 2017