



KOCH EXPLORATION COMPANY, LLC

January 13, 2017

Colorado Oil & Gas Conservation Commission
Mr. Craig Burger
Northwest Engineer
craig.burger@state.co.us

1120 Lincoln Street, Suite 801
Denver, CO 80203

WARNING LETTER # 401183850
WRD FEDERAL 2-23 (API# 103-10988)
NWSE, 23, 2N, 97W, RIO BLANCO

Mr. Burger,

Koch Exploration Company has reviewed the circumstances around the casing repair work done on the WRD FEDERAL 2-23 well. We have reviewed and updated our procedures for commencing well work, including identifying the types of well interventions that require prior approval from regulatory authorities, and we have trained our staff on those procedures. We are comfortable that the updated procedures will prevent recurrence of this alleged violation.

Sincerely,

A handwritten signature in blue ink, appearing to read "D. Howard".

Douglas Howard
VP Operations
Koch Exploration Company, LLC
(303) 325-2562
howard4d@kochind.com

303.325.2560 Tel
303.325.2599 Fax

950 17th Street, Suite 1900
Denver, Colorado 80202