



OUTCOME NOTICE for WARNING LETTER # 401168076

01/24/2017

CRESTONE PEAK RESOURCES OPERATING LLC (# 10633)

Jason Oates

jason.oates@crestonepr.com

370 17TH STREET #2170

DENVER, CO 80202

Re: Warning Letter # 401168076

Date Issued 12/16/2016

ERIE CHAMPLIN 18-9 (API# 123-19083)

NESE, 18, 1N, 68W, WELD

This Outcome Notice is to inform you of the status of the violation(s) alleged in the above referenced Warning Letter.

Alleged Violation(s) and Required Corrective Action(s):

803 Lighting

Description of Alleged Violation: Pursuant to Rule 803, Crestone Peak Resources Operating LLC (Operator) is required, to the extent practicable, to direct site lighting downward and inward and shielded so as to avoid glare on public roads and building units within one thousand (1,000) feet. On December 11 and 13, 2016, COGCC staff received complaints (Complaint Numbers 200440714, 200440679 , 200440685 , 200440687 , 200440688 , and 200440689) regarding light from Operator's Erie Champlin #18-9 well location, API 123-19083, (Erie Champlin) glaring on surrounding building units.

On December 12, 2016, COGCC staff inspected Erie Champlin and observed a potential violation of Rule 803 lighting requirements (Document #672500237). The inspection was conducted during daylight hours, but the angle of the lights appeared to be directed in a manner that allowed light to glare on surrounding building units, violating Rule 803.

Document #672500237 included a corrective action for Operator to bring lighting into compliance with the requirements of Rule 803 by December 13, 2016. COGCC staff returned to Erie Champlin the evening of December 12, 2016 and confirmed that Operator had adjusted the lights to comply with Rule 803 (Document # 672500251).

Required Corrective Action: Operator must comply with the lighting requirements of Rule 803 during the course of all future operations. Corrective action for the present matter has already been completed, and Operator is not required to respond to this letter or submit evidence of completed Corrective Actions.





Corrective Action Deadline Date: 12/16/2016

Corrective Action Performed by Operator

Description: This Warning Letter contained no affirmative corrective actions.

Completion Date: 12/19/2016

Outcome of Warning Letter # 401168076: No Further Action Required

This Warning Letter contained no affirmative corrective actions. Operator must comply with the lighting requirements of Rule 803 during the course of all future operations.

Other Violations:

If COGCC has reasonable cause to believe that CRESTONE PEAK RESOURCES OPERATING LLC has additional violations not addressed through the above referenced Warning Letter, the COGCC may issue a Notice of Alleged Violation and seek penalties pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. COGCC may or may not elect to issue Warning Letters for additional instances of non-compliance based on the guidance of the COGCC Enforcement Guidance and Penalty Policy (Corrected 4/8/2015) and COGCC Rules.

Sincerely,

Dave Kulmann
Deputy Director - Field O
(303)894-2100x5189
dave.kulmann@state.co.us

Attachments

View Attachments in Imaged Documents on COGCC website <http://ogccweblink.state.co.us/> Search by Document Number.

Document Number Description

401168076	WARNING LETTER OUTCOME NOTICE
401170516	WARNING LETTER ISSUED
401170517	WARNING LETTER CERTIFIED MAIL RECEIPT
401170518	WARNING LETTER IN PROCESS
401173488	WARNING LETTER CERTIFIED MAIL RETURN RECEIPT

Total Attach: 5 Files

