

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401190352

Date Received:

01/20/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Owen Williams

970-304-5000

owen.williams@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682401636

Inspection Date: 12/13/2016

FIR Submit Date: 12/23/2016

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 432532

Location Name: LC24-01 Number: PAD County: _____

Qtrqtr: NENE Sec: 24 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.742710 Longitude: -103.918720

FACILITY - API Number: 05-123-00 Facility ID: 432532

Facility Name: LC24-01 Number: PAD

Qtrqtr: NENE Sec: 24 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.742710 Longitude: -103.918720

CORRECTIVE ACTIONS:

1 CA# 54715

Corrective Action: Perform one of the two corrective actions:

Date: 01/20/2017

1) Provide construction calculations from the site specific stormwater plan demonstrating that the installed BMPs described above are sufficient to prevent sediment laden storm runoff from leaving location

or,

2) Install sufficient BMPs in accordance with good engineering practices per Rule 1002.f.

Response: CA COMPLETED

Date of Completion: 01/20/2017

Operator Comment: Diversion ditches and sediment traps were initially installed on 11/9/2016. Sediment traps are installed at the outlet of diversion ditches to allow sediment to settle out of stormwater runoff and used for drainage areas less than ten acres. Multiple sediment traps have been installed on location, estimated disturbance area of 6.4 acres

COGCC Decision: **Not Approved**

COGCC Representative: This response does not address the Corrective Action to demonstrate that the installed BMPs are sufficient. Corrective Action still remains open.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Owen Williams

Signed: _____

Title: 970-304-5000

Date: 1/20/2017 2:18:53 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401190352	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files