

2016 Rangely Weber Sand Unit Release Summary

Spill Date	Location	Substance	Root Cause	Category	Flowline	Oil Spilled	Water Spilled
1-Feb-16	EM 9	Inj. Water	Internal Corrosion	Spool	Yes	0.0	82.9
5-Feb-16	FV Larson B-11	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	5.1
20-Mar-16	Gray B-7	Inj. Water	Internal Corrosion	Spool	Yes	0.0	55.3
22-Mar-16	SB Lacy 12Y	Prod. Fluids	Internal Corrosion	Water Injection Line	Yes	0.3	57.6
5-Apr-16	AC McL 45	Inj. Water	Internal Corrosion	Spool	Yes	0.0	54.4
10-Apr-16	EM 22	Inj. Water	Internal Corrosion	Water Injection Line	Yes	0.0	47.3
25-May-16	ACM 55X	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	4.9
26-May-16	Magor 1	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	21.0
31-May-16	Fee64	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	484.4
26-Jun-16	Carney 27 X34	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	12.6
3-Jul-16	MWP (Ruben Tank)	Prod. Fluids	Internal Corrosion	Process Facility	No	0.2	88.1
12-Jul-16	AC McL 56X	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	182.0
22-Jul-16	Carney 33-34	Inj. Water	Internal Corrosion	Spool	Yes	0.0	21.0
27-Jul-16	Levison 13	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	4.0
8-Aug-16	Carney 41Y34	Prod. Fluids	Weather	Sump	No	0.6	201.0
10-Aug-16	Fee 73X	Prod. Fluids	Weather	Production Flowline	Yes	29.3	229.1
11-Aug-15	Fee 145Y Rain Water Filled Location	Prod. Fluids	Weather	Sump	No	0.0	63.4
13-Aug-16	Fee 49	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	1918.0
14-Aug-16	UP 10-21	Prod. Fluids	Rupture	Water Injection Line	Yes	0.2	7.2
15-Aug-16	UP 25-34	Prod. Fluids	Rupture	Production Flowline	Yes	0.8	16.3
22-Aug-16	Carney 41y34	Prod. Fluids	Rupture	Abandoned Line	No	0.0	60.0
30-Aug-16	AC McL 44	Prod. Fluids	Internal Corrosion	Water Injection Line	Yes	0.0	86.6

8-Sep-16	UP 21X32	Inj. Water	External Corrosion	Abandoned Line	No	0.0	46.0
22-Sep-16	UP 128X31	Prod. Fluids	Internal Corrosion	Production Flowline	Yes	1.8	30.3
5-Dec-16	Fee 19	Prod. Fluids	Internal Corrosion	Production Flowline	Yes	1.1	20.4
11-Dec-16	AC McL 43	Inj. Water	Internal Corrosion	Spool on Location	Yes	0.0	90.0
15-Dec-16	Fee 43	Inj. Water	Internal Corrosion	Water Injection Line	Yes	0.0	335.0
21-Dec-16	CS 1	Prod. Fluids	Internal Corrosion	Process Facility	No	0.0	15.5
28-Dec-16	CS 12	Prod. Fluids	Flow Cut / Erosion / Wear	Process Facility	No	0.0	12.2
31-Dec-16	MWP	Prod. Fluids	Internal Corrosion	Water Injection Line	Yes	0.0	28.4
31-Dec-16	UP 45-21	Inj. Water	Internal Corrosion	Water Injection Line	Yes	0.0	74.9