

STATE OF
COLORADO

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>

Butterball 32C-34HZ doc no 401162764

4 messages

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>
To: "Marshall, Shayelyn" <Shayelyn.marshall@anadarko.com>
Cc: "Cheryl.light" <Cheryl.light@anadarko.com>

Thu, Jan 19, 2017 at 11:15 AM

Shaye,

COGCC is in the process of reviewing the Form 2A for the Butterball 32C-34HZ location (doc no 4011627643). In order to complete our review, please address the following:

1. While the location is located in unincorporated Weld County, County Road 24 does is partially in the jurisdiction of Firestone. Please be sure all jurisdictions are aware of truck routes.
2. The disturbed area size on the location drawing does not appear to match the disturbed area on the Form 2A. Please confirm how much land will be disturbed before interim reclamation.
3. The well HSR-STREAR 4-10A, API 05-123-19595 and Location 330770, appears to be in the disturbed area. While this well is shut in, it has not been abandoned and therefore should be included in the well count. COGCC would like to make this an amended location for 330770. With your concurrence, I will change the facilities to 5 wells and update to an amended location for 330770. If Kerr-McGee has a reason for this to be a new location, please let me know and we can discuss further.
4. The nearest building unit appears to be owned by the surface owner. Please provide correspondence regarding the distance of the wells to the building unit.

Let me know if there are questions or would like to discuss the above further.

--
Rebecca Treitz
Oil and Gas Location Assessment Specialist
P 303.894.2100 x5173 | F 303.894.2109 |
1120 Lincoln Street, Suite 801, Denver, CO 80203
Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

Light, Cheryl <Cheryl.Light@anadarko.com>
To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>
Cc: "Marshall, Shayelyn" <Shayelyn.Marshall@anadarko.com>

Fri, Jan 20, 2017 at 3:37 PM

1. While the location is located in unincorporated Weld County, County Road 24 does is partially in the jurisdiction of Firestone. Please be sure all jurisdictions are aware of truck routes.

Our municipal planning team will contact Firestone regarding access and truck routes when we acquire our access permits.

2. The disturbed area size on the location drawing does not appear to match the disturbed area on the Form 2A. Please confirm how much land will be disturbed before interim reclamation.

Please revise the acreage to 6.25 acres

3. The well HSR-STREAR 4-10A, API 05-123-19595 and Location 330770, appears to be in the disturbed area. While this well is shut in, it has not been abandoned and therefore should be included in the well count. COGCC would like to make this an amended location for 330770. With your concurrence, I will change the facilities to 5 wells and update to an amended location for 330770. If Kerr-McGee has a reason for this to be a new location, please let me know and we can discuss further.

Yes, please change this location to an amended one and add the HSR to the well count.

4. The nearest building unit appears to be owned by the surface owner. Please provide correspondence regarding the distance of the wells to the building unit.

As we stated in our comments the property is for sale and we placed the wells to not use any of the space he wants for the sale. The 3 units are all tenants on a month to month contract. Our Surface Landman and our Stakeholder Relations group will both engage with the tenants as we get closer to the drilling time.

From: Treitz - DNR, Rebecca [<mailto:rebecca.treitz@state.co.us>]

Sent: Thursday, January 19, 2017 11:15 AM

To: Marshall, Shayelyn

Cc: Light, Cheryl

Subject: Butterball 32C-34HZ doc no 401162764

Shaye,

COGCC is in the process of reviewing the Form 2A for the Butterball 32C-34HZ location (doc no 4011627643). In order to complete our review, please address the following:

1. While the location is located in unincorporated Weld County, County Road 24 does is partially in the jurisdiction of Firestone. Please be sure all jurisdictions are aware of truck routes.

Our municipal planning team will contact Firestone regarding access and truck routes.

2. The disturbed area size on the location drawing does not appear to match the disturbed area on the Form 2A. Please confirm how much land will be disturbed before interim reclamation.

Please revise the acreage to (3 acres??) → WAITING TO HEAR BACK FROM PAUL

3. The well HSR-STREAR 4-10A, API 05-123-19595 and Location 330770, appears to be in the disturbed area. While this well is shut in, it has not been abandoned and therefore should be included in the well count. COGCC would like to make this an amended location for 330770. With your concurrence, I will change the facilities to 5 wells and update to an amended location for 330770. If Kerr-McGee has a reason for this to be a new location, please let me know and we can discuss further.

Yes, please change this location to an amended one and add the HSR to the well count.

4. The nearest building unit appears to be owned by the surface owner. Please provide correspondence regarding the distance of the wells to the building unit.

Correspondence includes: → WAITING TO HEAR BACK FROM PAUL

Let me know if there are questions or would like to discuss the above further.

--

Rebecca Treitz

Oil and Gas Location Assessment Specialist

P 303.894.2100 x5173 | F 303.894.2109 |

1120 Lincoln Street, Suite 801, Denver, CO 80203

Rebecca.Treitz@state.co.us | www.colorado.gov/cogcc

[Click here for Anadarko's Electronic Mail Disclaimer](#)

Treitz - DNR, Rebecca <rebecca.treitz@state.co.us>
To: "Light, Cheryl" <Cheryl.Light@anadarko.com>
Cc: "Marshall, Shayelyn" <Shayelyn.Marshall@anadarko.com>

Mon, Jan 23, 2017 at 1:22 PM

Thanks,
Please send the 306.e. certification when you are ready.

Rebecca
[Quoted text hidden]

Marshall, Shayelyn <Shayelyn.Marshall@anadarko.com> Tue, Jan 24, 2017 at 3:25 PM
To: "Treitz - DNR, Rebecca" <rebecca.treitz@state.co.us>, "Light, Cheryl" <Cheryl.Light@anadarko.com>

Hi Rebecca,

Please see the 306.e letter attached and let me know if you have any questions.

Thank you!
Shaye

From: Treitz - DNR, Rebecca [mailto:rebecca.treitz@state.co.us]
Sent: Monday, January 23, 2017 1:23 PM
To: Light, Cheryl
Cc: Marshall, Shayelyn
Subject: Re: FW: Butterball 32C-34HZ doc no 401162764

[Quoted text hidden]



BUTTERBALL 32C-34HZ 306.e and 306.b.(3) CERTIFICATION.pdf
134K