

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2017

Submitted Date:

02/02/2017

Document Number:

682600256**FIELD INSPECTION FORM**
 Loc ID 439367 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUS-TEX EXPLORATION INCAddress: 113 N SANTA FECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Goss, Aaron	303-233-2232/303-495-0327	AGoss@austineexploration.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	XX	06/08/2016	OW	043-06227	Columbus 1	EI

**General Comment:**

This inspection is a follow up to inspection 682600234 conducted on 11-8-2016 which identified 2 corrective actions. 1) fence pit and 2) install stormwater BMP's per Rule 1002.f

Fencing has been fixed but stormwater controls have not been installed (wattles were present on location but not yet installed - see attached photos).

Drilling pit closure: Operator shall comply with applicable COA's on permit. Per Rule 1003.d.(2) operator shall ensure closure and reclamation of drilling pit no later than six (6) months after drilling and completion activities conclude, weather permitting.



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: **ALLEGED VIOLATION - Stormwater BMP's were not installed by Corrective Action deadline of 12/8/16 established on inspection 682600234.**

Corrective Action: **Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.** Date: 12/08/2016

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Operator shall submit Form 27 to the area Environmental Protection Specialist (EPS) to document closure of drilling pit. Operator shall comply with applicable COA's on permit outlining pit closure. Operator shall remove pit liner and obtain soil samples from bottom of pit to document compliance with COGCC Table 910-1. Sample results shall be submitted on the Form 27.	kosolaj	02/02/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600257	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4066603</a>