

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/23/2017

Submitted Date:

02/03/2017

Document Number:

680301584**FIELD INSPECTION FORM**
 Loc ID 312310 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 94300Name of Operator: WARD & SON* ALFREDAddress: P O BOX 737City: OGALLALLA State: NE Zip: 69153**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
Quint, Craig		craig.quint@state.co.us	
Ward, Randy	308-284-8350	rlwardne@charter.net	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221174	WELL	PR	10/04/1996	OW	075-09300	STATE 5	PR

General Comment:

FIR - Reference Doc# 663300122 dated 06/04/2012, 663300444 dated 8/17/2012 & 664001035 dated 6/10/2013 for CA dates.

Contact COGCC Environmental Group (John Axelson) for directives to resolve former Skim pit closure (current site of PW/Skim tank) concerns and current PW/Skim pit remediation a.s.a.p. upon receipt of this FIR.

Location			
Lease Road:			
Type	Access		
comment:	Satisfactory		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:	Comply with rule 210.		Date: 08/31/2012
Type	WELLHEAD		
Comment:	No sign @ wellhead. Reference Doc#663300444 & 664001035 for CA dates.		
Corrective Action:	Place sign at wellhead per Rule 210.		Date: 08/31/2012
Emergency Contact Number:			
Comment:	Emergency contact no. received by answering machine. Reference Doc# 663300444 & 664001035 for CA dates.		
Corrective Action:			Date: 08/30/2012
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil		<= 1 bbl	
Comment:	Free crude on surface of PW/Skim pit and inside edge of berm.		
Corrective Action:	Remove/remediate free oil on surface of PW/Skim pit and inside edge soils of pit. Removal of hydro-carbons on surface of PW/Skim pit cited on document #664001035 dated 06/10/2013 requiring removal within (24) hours of notification. Contact COGCC Environmental Group for directives.		Date: 08/30/2012
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	propane tank		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Pump Jack	# 1	
Comment: Lufkin NG Engine		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:	Placard all tanks in compliance with rule 210. Reference Doc#663300444				Date: 08/31/2012

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	Restore, reconstruct, size appropriately, berms at tank battery and PW/Skim tank containment.			
Corrective Action:	Restore, reconstruct, size appropriately, berms at tank battery and PW/Skim tank containment.			Date: 02/17/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.918220,-103.264030
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	221174	Type:	WELL	API Number:	075-09300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Please read FIR completely and comply with CA dates and responses to COGCC Environmental Group immediately upon receipt of this FIR of a.s.a.p. thereafter.								
Corrective Action:							Date:		

--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Use BMP's for stormwater erosion management](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401202323	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068309
680301653	Tank Signage - No content / Capacity placarding	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068296
680301654	Tank Signage - No contents / Capacity placarding	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068297
680301656	Tank Signage No content/capacity + No sign at PJ	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068298
680301657	NFPA placard	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068299
680301658	PW/Skim tank - No content/capacity	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068300
680301659	NFPA placard	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068301
680301660	Inadequate berm at PW/Skim tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068302
680301661	Free crude on surface of PW/Skim pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068303
680301662	Fred crude on surface of PW/Skim pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068304
680301663	Residue on floor of overflow PW pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068305
680301664	Oil stained soil on inside edge of PW/Skim pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068306
680301665	Oil stained soil on inside edge of PW/Skim pit berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4068307