

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401156064
Date Received:
11/28/2016

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685301808
Inspection Date: 11/14/2016 FIR Submit Date: 11/15/2016 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326167

Location Name: THOMAS JACQUEZ GAS UNIT E-N33N10W Number: 14NESE County: LA PLATA
Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.103177 Longitude: -107.898299

FACILITY - API Number: 05-067-00 Facility ID: 215984

Facility Name: THOMAS JACQUEZ E Number: 1
Qtrqr: NESE Sec: 14 Twp: 33N Range: 10W Meridian: N
Latitude: 37.103177 Longitude: -107.898299

CORRECTIVE ACTIIONS:

1 CA# 54064

Corrective Action: Locate and mark all deadmen to comply with Rule 1003.a Date: 11/30/2016

Response: CA COMPLETED Date of Completion: 11/21/2016

Operator Comment: Removed wood wire spool, marked rig anchor, replaced location sign, and installed road construction barrel correctly with dirt around bottom for stability.

COGCC Decision: Approved

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

2 CA# 54065

Corrective Action: Remove the debris from location to comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 11/25/2016

Response: CA COMPLETED

Date of Completion: 11/21/2016

Operator Comment: Removed wood wire spool, marked rig anchor, replaced location sign, and installed road construction barrel correctly with dirt around bottom for stability.

COGCC Decision: Approved

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Removed wood wire spool, marked rig anchor, replaced location sign, and installed road construction barrel correctly with dirt around bottom for stability.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: _____

Title: Compliance Specialist Date: 11/28/2016 7:47:31 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401156064	FIR RESOLUTION SUBMITTED
401156067	CA Closure documentation

Total Attach: 2 Files