

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401203523
Date Received:
02/09/2017

FIR RESOLUTION FORM

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685302106
Inspection Date: 01/11/2017 FIR Submit Date: 01/12/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306819

Location Name: KRAJACK GAS UNIT 43-27-M34N8W Number: 27SWSE County: LA PLATA
Qtrqr: SWSE Sec: 27 Twp: 34N Range: 8W Meridian: M
Latitude: 37.155646 Longitude: -107.704289

FACILITY - API Number: 05-067-00 Facility ID: 268649

Facility Name: KRAJACK 43-27 Number: 2
Qtrqr: SWSE Sec: 27 Twp: 34N Range: 8W Meridian: M
Latitude: 37.155646 Longitude: -107.704289

CORRECTIVE ACTIIONS:

1 CA# 59007

Corrective Action: Repair or install sign to comply with Rule 210.b. Date: 03/14/2017

Response: CA COMPLETED Date of Completion: 02/06/2017

Operator Comment: New sign has been installed on location please refer to attached documentation.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

2 CA# 59008

Corrective Action: Remove barriers to comply with Rule 603.f using the Rule 603.f guidance document for further details. Date: 02/12/2017

Response: CA COMPLETED Date of Completion: 01/30/2017

Operator Comment: Operator Debris Jersey Barriers have been removed from location. Land owner debris has been removed from location see attached documentation.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

3 CA# 59009

Corrective Action: Repair or install sign to comply with Rule 210.d. Date: 03/14/2017

Response: CA COMPLETED Date of Completion: 02/06/2017

Operator Comment: Signs on location have been replaced with new signs see attached documentation.

COGCC Decision: Approved via an AMI

COGCC Representative: Photo documentation provided by Operator shows corrective action completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions on this location have been addressed and corrected see attached documentation

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: _____

Title: Compliance Specialist Date: 2/9/2017 10:12:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401203523	FIR RESOLUTION SUBMITTED
401206224	Debris removal documentation
401206226	New sign documentation

Total Attach: 3 Files