



STATE OF  
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

---

## Flowline Failure on the SLW Ranch 24, 34, 44-7

---

**Zack Liesenfeld** <Zack.Liesenfeld@pdce.com>  
To: "Allison - DNR, Rick" <rick.allison@state.co.us>  
Cc: "Jason E. Thron" <Jason.Thron@pdce.com>

Wed, Feb 22, 2017 at 8:28 AM

Morning Rick,

Wanted to let you know last week (2.16.2017) PDC discovered a flowline failure on the **SLW Ranch 24, 34, 44-7** Location ID 330885. Gauging showed approximately 1.5 inch of fluid lost from the water vault which equates to approximate 1.5 bbl of water being released. Upon discovery the facility was immediately shut in and vault bottomed out. Excavation activities have not yet begun, thus PDC is unsure if this release is reportable. Once repair efforts have commenced and this release is determined reportable, notification will be made to the COGCC and landowner.

Please let me know if you have any questions or concerns.

Thanks,

Zack

**Zack Liesenfeld**

Evans, Colorado

O: [970.506.9272](tel:970.506.9272)

C: [970.373.6581](tel:970.373.6581)

[Zack.Liesenfeld@pdce.com](mailto:Zack.Liesenfeld@pdce.com)



[www.pdce.com](http://www.pdce.com)

NASDAQ: PDCE

