

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401221912

Date Received:

03/01/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Cynthia Stowell

303-813-6133

cogccinspection@pdce.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682401789

Inspection Date: 02/15/2017

FIR Submit Date: 02/17/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 445139

Location Name: Cecil's Kersey Farm Number: 5N64W17B County: \_\_\_\_\_

Qtrqr: NWS Sec: 17 Twp: 5N Range: 64W Meridian: 6  
W

Latitude: 40.396743 Longitude: -104.580386

### FACILITY - API Number: 05-123- -00 Facility ID: 445139

Facility Name: Cecil's Kersey Farm Number: 5N64W17B

Qtrqr: NWS Sec: 17 Twp: 5N Range: 64W Meridian: 6  
W

Latitude: 40.396743 Longitude: -104.580386

### CORRECTIVE ACTIONS:

1 ☒ CA# 64831

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 03/17/2017

Response: CA COMPLETED

Date of Completion: 03/01/2017

Operator Comment: Attached are photos of the resolved Stormwater issues identified in the COGCC inspection of Cecil Kersey Farms. All Corrective Actions have been installed or repaired per the inspection request. Thank you.

COGCC Decision: Approved via an AMI

COGCC Representative: Operator provided sufficient photo documentation to demonstrate that corrective actions from FIR Document #682401789 to install or repair required BMPs per Rule 1002.f. have been performed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Attached are photos of the resolved Stormwater issues identified in the COGCC inspection oof Cecil Kersey Farms. All Corrective Actions have been installed or repaired per the inspection request. Thank you.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cynthia Stowell

Signed: \_\_\_\_\_

Title: EHS Professional

Date: 3/1/2017 9:41:34 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401221912	FIR RESOLUTION SUBMITTED
401221920	Photo1
401221924	Photo2
401221925	Photo3
401221926	Photo4
401221939	Photo5

Total Attach: 6 Files