



Sec. 15

LINE TABLE			LINE TABLE		
LINE	DIRECTION	LENGTH	LINE	DIRECTION	LENGTH
L1	S00°14'25"E	270.96'	L14	S00°19'17"E	15.04'
L2	S00°15'47"E	250.98'	L15	N59°44'28"E	245.66'
L3	S00°14'13"E	249.85'	L16	N59°12'14"E	258.49'
L4	S00°15'47"E	170.36'	L17	N89°48'49"E	277.39'
L5	S00°25'46"E	188.71'	L18	N89°48'49"E	320.50'
L6	S00°23'10"E	206.26'	L19	S69°55'13"W	86.77'
L7	S00°27'06"E	305.79'	L20	EAST	59.34'
L8	S00°27'06"E	150.99'	L21	EAST	195.29'
L9	S00°32'22"E	117.34'	L22	EAST	206.66'
L10	S00°15'47"E	97.42'	L23	S89°07'48"W	52.30'
L11	S00°14'13"E	96.54'	L24	S89°49'02"E	559.39'
L12	S00°23'10"E	50.86'	L25	N89°56'43"W	127.76'
L13	S00°25'46"E	32.75'	L26	S89°49'02"E	402.95'

1/4 Section Line

500' Offset
from Edge of
Disturbance

Kenyon K.
Ayars

PROPOSED #511-1510H
(NAD 83)
Lat: 40.915956°
Long: 104.415347°

500'

PROPOSED #232-1510H
(NAD 83)
Lat: 40.915969°
Long: 104.412814°

1/16 Section Line



Kenyon K.
Ayars

SW Cor. Sec. 15
2009 Alum. Cap.
#17492

S 1/4 Cor. Sec. 15,
2009 Alum. Cap.
0.4' Below Ground

Section Line

PLANT COMMUNITY

- ☐ DISTURBED GRASSLAND
☒ NATIVE GRASSLAND
☐ SHRUB LAND
☐ PLAINS RIPARIAN
☐ MOUNTAIN RIPARIAN
☐ FOREST LAND
☐ WETLANDS AQUATIC
☐ ALPINE
☐ OTHER (Describe): _____

Sec. 22



OASIS RANCH LLC

OASIS RANCH LLC

FUTURE LAND USE

- CROP LAND: ☐ IRRIGATED ☐ DRY LAND ☐ IMPROVED PASTURE ☐ HAY MEADOW ☐ CRP
NON-CROP LAND: ☒ RANGELAND ☐ TIMBER ☐ RECREATIONAL ☐ OTHER (Describe) _____
SUBDIVIDED: ☐ INDUSTRIAL ☐ COMMERCIAL ☐ RESIDENTIAL _____

CURRENT LAND USE

- CROP LAND: ☐ IRRIGATED ☐ DRY LAND ☐ IMPROVED PASTURE ☐ HAY MEADOW ☐ CRP
NON-CROP LAND: ☒ RANGELAND ☐ TIMBER ☐ RECREATIONAL ☐ OTHER (Describe) _____
SUBDIVIDED: ☐ INDUSTRIAL ☐ COMMERCIAL ☐ RESIDENTIAL _____

REV: 1 01-24-17 T.B. (PAD CHANGE & ADD WELLS)

FIFTH CREEK ENERGY COMPANY, LLC

CRITTER CREEK 15 SE
S 1/2 SE 1/4, SECTION 15, T11N, R63W, 6th P.M.
WELD COUNTY, COLORADO

SURVEYED BY	GREG WEIMER., N.P.	01-20-17	SCALE
DRAWN BY	T.B.	04-02-15	1" = 200'
LOCATION DRAWING		FIGURE #4	



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017