



STATE OF  
COLORADO

Allison - DNR, Rick <[rick.allison@state.co.us](mailto:rick.allison@state.co.us)>

---

## Noble 24hr Notice

1 message

---

**Jacob Evans** <[Jacob.Evans@nblenergy.com](mailto:Jacob.Evans@nblenergy.com)>

Fri, Mar 17, 2017 at 11:23 AM

To: Rick Allison <[rick.allison@state.co.us](mailto:rick.allison@state.co.us)>

Cc: Roy Rudisill <[rrudisill@co.weld.co.us](mailto:rrudisill@co.weld.co.us)>, Ellice Hazard - DNR <[Ellice.Hazard@state.co.us](mailto:Ellice.Hazard@state.co.us)>, "Maclaren - DNR, Joe" <[joe.maclaren@state.co.us](mailto:joe.maclaren@state.co.us)>

Rick,

Noble discovered an unintentional release associated with the Brown 20-12, English 31-10 location. The produced water line developed a leak. The facility is shut in and remediation/repairs are currently underway.

05-123-22068

Jacob

Jacob Evans

Environmental Coordinator

EHSR

direct: [970.304.5329](tel:970.304.5329)

cell: [303.328.5605](tel:303.328.5605)

Please note my new email address: [Jacob.Evans@nblenergy.com](mailto:Jacob.Evans@nblenergy.com)

