

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2017

Submitted Date:

03/22/2017

Document Number:

675204043

**FIELD INSPECTION FORM**

Loc ID 312411 Inspector Name: CONKLIN, CURTIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 64300  
Name of Operator: NORTHSTAR RESOURCES, INC  
Address: SUITE 1490  
City: HOUSTON State: TX Zip: 77024

**Findings:**

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor
Zachary, Casey		ccaseyzachary@aol.com	Ops Manager
Lujan, Carlos		carlos.lujan@state.co.us	
Engineering		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
McKenny, Ken	(832) 421-4775	kkmacgas@conertric.net	President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221521	WELL	SI	05/06/1978	GW	077-08122	FEDERAL 32-3	PA

**General Comment:**

Well was plugged on 5/24/16 according to BLM records submitted to COGCC area engineer. No notification for plugging, Form 10, Form 27 or Form 6 was submitted by operator. NOAV Resolution Doc#400950525 says "Well has been plugged and abandoned as required". Separator is still on site with no evidence of other equipment. No evidence of Final reclamation.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	No well marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Separator has been disconnected and relocated on site.		
Corrective Action:	Remove separator per Rule 1004.a.	Date:	08/24/2016

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 221521 Type: WELL API Number: 077-08122 Status: SI Insp. Status: PA

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined:                      Pit ID:                      Lat: 39.323456                      Long: -109.015419

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type:    Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:                      Oil Accumulation:                      2+ feet Freeboard:

Comment: Pit had no COGCC permit. Pit has been closed. No documentation submitted to COGCC

Corrective Action

Contact COGCC EPS staff for directives per Rule 905.b.

Date: 08/24/2016

Type: Blowdown                      Lined:                      Pit ID: 116440                      Lat: 39.323456                      Long: -109.015419

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type:    Fencing Condition:

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:    Netting Condition: \_\_\_\_\_

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	Pit has been closed. No documentation submitted to COGCC	
Corrective Action	Contact COGCC EPS staff for directives per Rule 905.b.	
		Date: 08/24/2016

<b>COGCC Comments</b>		
Comment	User	Date
	conklinc	03/22/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675204044	Federal 32-3 March 21, 2017	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4105501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4105501</a>