

FORM 5A Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 401101513 Date Received: 11/08/2016

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reoperation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 10447 2. Name of Operator: URSA OPERATING COMPANY LLC 3. Address: 1050 17TH STREET #1700 City: DENVER State: CO Zip: 80265 4. Contact Name: JENNIFER LIND Phone: (720) 508-8362 Fax: Email: JLIND@URSARESOURCE.COM

5. API Number 05-045-22914-00 6. County: GARFIELD 7. Well Name: MONUMENT RIDGE B Well Number: 43C-08-07-95 8. Location: QtrQtr: SESE Section: 8 Township: 7S Range: 95W Meridian: 6 9. Field Name: PARACHUTE Field Code: 67350

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type: FRACTURE STIMULATION Treatment Date: 07/08/2016 End Date: 07/26/2016 Date of First Production this formation: 07/31/2016 Perforations Top: 4036 Bottom: 6863 No. Holes: 540 Hole size: 0.37

Provide a brief summary of the formation treatment: Open Hole: [] Frac'd with 151,140 bbls 2% slickwater and no proppant. Frac pair with Monument Ridge B 23C-08-07-95 (API 05-045-22963) and Monument Ridge B 33B-08-07-95 (API 05-045-22903).

This formation is commingled with another formation: [] Yes [X] No Total fluid used in treatment (bbl): 151140 Max pressure during treatment (psi): 7699 Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal): 8.40 Type of gas used in treatment: Min frac gradient (psi/ft): 0.69 Total acid used in treatment (bbl): Number of staged intervals: 10 Recycled water used in treatment (bbl): 151140 Flowback volume recovered (bbl): 51188 Fresh water used in treatment (bbl): Disposition method for flowback: RECYCLE Total proppant used (lbs): Rule 805 green completion techniques were utilized: [X] Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 08/26/2016 Hours: 24 Bbl oil: 0 Mcf Gas: 2807 Bbl H2O: 1059 Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 2807 Bbl H2O: 1059 GOR: 0 Test Method: Flowing Casing PSI: 550 Tubing PSI: 1200 Choke Size: 64 Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1044 API Gravity Oil: 0 Tubing Size: 2 + 3/8 Tubing Setting Depth: 5437 Tbg setting date: 07/31/2016 Packer Depth: Reason for Non-Production: Date formation Abandoned: Squeeze: [] Yes [] No If yes, number of sacks cmt ** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

Comment:

Wellbore diagram attached. TPZ FOOTAGES PROVIDED ON THE ASSOCIATED FORM 5 ARE ACTUAL FOOTAGES BASED ON COMPLETED WELLBORE DATA.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: JENNIFER LIND

Title: REGULATORY ANALYST Date: 11/8/2016 Email JLIND@URSARESOURCES.COM

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401101513	FORM 5A SUBMITTED
401101559	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Passes permitting.	03/28/2017
Permit	Ready to pass pending the correction of the related Form 5.	03/27/2017
Permit	Returned to draft. Perforated interval is incorrect-Perforated depth cannot surpass the TD value. Min frac gradient value is missing. Please add a comment stating the as-drilled TPZ footages and an explanation for the delayed completions.	10/27/2016

Total: 3 comment(s)