

<b>FORM INSP</b> Rev X/15	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		Inspection Date: <u>03/27/2017</u> Submitted Date: <u>03/31/2017</u> Document Number: <u>682401956</u>
<b>FIELD INSPECTION FORM</b>			

Loc ID 446137	Inspector Name: Binschus, Chris	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
------------------	------------------------------------	---	-------------------	---

**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446138	WELL	XX	06/11/2016		123-43260	HILGERS 32N-22HZ	CI
446139	WELL	XX	06/11/2016		123-43261	HILGERS 12N-22HZ	CI
446140	WELL	XX	06/11/2016		123-43262	HILGERS 33N1-22HZ	CI

**General Comment:**

[This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401220478.](#)

**Location Construction**

Location ID: 446137 CDP: \_\_\_\_\_

**Comment:** Topsoil salvaged, stored, and temporarily stabilized along the southern location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** An area of 5.88 acres was mapped on 3/27/2017 using a Trimble Juno 3B handheld device.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

<b>DITCHES</b>	Yes				
Comments: Erosion BMPs: <span style="border: 1px solid black; padding: 2px;">Ditch BMP installed around north, west, and south perimeter of location.</span>					
Other BMPs: <span style="border: 1px solid black; display: inline-block; width: 100%; height: 15px;"></span>					
Corrective Action: _____ Date: _____					
<b>BERMS</b>	Yes	Vehicle Trakcing	Yes`		
Comments: Erosion BMPs: <span style="border: 1px solid black; padding: 2px;">Berm BMP installed around north, west, and south perimeter of location.</span>					
Other BMPs: <span style="border: 1px solid black; display: inline-block; width: 100%; height: 15px;"></span>					
Corrective Action: _____ Date: _____					
<b>RETENTION PONDS</b>	Yes				
Comments: Erosion BMPs: <span style="border: 1px solid black; padding: 2px;">Two (2) sediment traps have been installed along the western and southwest perimeter of location with outlet protection in the form of a blanket and wattle.</span>					
Other BMPs: <span style="border: 1px solid black; display: inline-block; width: 100%; height: 15px;"></span>					
Corrective Action: _____ Date: _____					

**Comment:** BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_  
 Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 446138 Type: WELL API Number: 123-43260 Status: XX Insp. Status: CI

Facility ID: 446139 Type: WELL API Number: 123-43261 Status: XX Insp. Status: CI

Facility ID: 446140 Type: WELL API Number: 123-43262 Status: XX Insp. Status: CI

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401957.</a>	binschusc	03/31/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401957	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113681">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113681</a>