



STATE OF  
COLORADO

Allison - DNR, Rick <rick.allison@state.co.us>

---

## Line leak BBC 70 Ranch 4-6-20

---

**Rusty Frishmuth** <rfrishmuth@billbarrettcorp.com>

Fri, Apr 7, 2017 at 3:17 PM

To: "rick.allison@state.co.us" <rick.allison@state.co.us>

Cc: "gmarquez@co.weld.co.us" <gmarquez@co.weld.co.us>

Rick - we have discovered a reportable flow line leak at our 70 Ranch 4-6-20 well which flows to our NHF Laura 1 battery which is on the west end of 70 Ranch down by the Platte River. API 05-123-26053. Pumper noted a loss of pressure and shut in the well. This morning we excavated an area 12\*24\*6.5' deep. LT Env was on location to direct excavation and we collected confirmation samples. No free fluid and no groundwater. Excavation still open pending receipt of lab results in Monday.

Will file a 19 on it over the weekend.

Sent from my iPhone