

# HALLIBURTON

iCem<sup>®</sup> Service

## **EXTRACTION OIL & GAS**

United States of America

Date: Monday, December 05, 2016

### **Mickey #1**

Surface

Job Date: Monday, November 14, 2016

Sincerely,

**Justin Lansdale**

## Legal Notice

---

### Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. Accordingly, HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

## Table of Contents

---

Cementing Job Summary .....	4
Executive Summary .....	4
Real-Time Job Summary .....	7
Job Event Log .....	7
Custom Graph.....	9

## 1.0 Cementing Job Summary

---

### 1.1 Executive Summary

---

Halliburton appreciates the opportunity to perform the cementing services on the **Mickey #1** cement **Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

**Halliburton [Fort Lupton]**

*The Road to Excellence Starts with Safety*

Sold To #: 369404		Ship To #: 3766593		Quote #:		Sales Order #: 0903665307					
Customer: EXTRACTION OIL & GAS -				Customer Rep: Larry Siegel							
Well Name: MICKEY			Well #: 1		API/UWI #: 05-123-43853-00						
Field: WATTENBERG		City (SAP): WINDSOR		County/Parish: WELD			State: COLORADO				
Legal Description: SW NE-5-6N-67W-2418FNL-1768FEL											
Contractor:				Rig/Platform Name/Num: Spud Rig							
Job BOM: 7521											
Well Type: HORIZONTAL OIL											
Sales Person: HALAMERICA\HX38199				Srvc Supervisor: Nathaniel Moore							
<b>Job</b>											
Job depth MD		1553 ft			Job Depth TVD						
<b>Well Data</b>											
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft	
Casing		9.625	8.921	36			0	1553	0	1553	
Open Hole Section			13.5				0	1560	0	1560	
<b>Tools and Accessories</b>											
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make		
Float Shoe	9.625			1553		Bottom Plug	9.625		HES		
<b>Fluid Data</b>											
Stage/Plug #: 1											
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal		
1	Red Dye Spacer	Red Dye Spacer	20	bbl	8.33						
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal		
2	SwiftCem	SWIFTCEM (TM) SYSTEM	525	sack	13.5	1.74		5	9.2		
9.20 Gal		<b>FRESH WATER</b>									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal		
3	Fresh Water	Fresh Water	117	bbl	8.33						

Cement Left In Pipe	Amount		Reason	Shoe Joint
	42 ft			

30 bbl cement to surface

## 2.0 Real-Time Job Summary

### 2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Comments
Event	1	Call Out	Call Out	11/14/2016	22:00:00	USER	Verify equipment and materials
Event	2	Depart Yard Safety Meeting	Depart Yard Safety Meeting	11/14/2016	00:30:00	USER	
Event	3	Assessment Of Location Safety Meeting	Assessment Of Location Safety Meeting	11/14/2016	01:30:00	USER	Rig laying down drill pipe. Spot equipment and rig up what we can.
Event	4	Pre-Job Safety Meeting	Pre-Job Safety Meeting	11/14/2016	08:40:00	USER	Discuss job procedure
Event	5	Start Job	Start Job	11/14/2016	09:00:57	COM1	Fill lines 3 bbl water. Circulation established
Event	6	Test Lines	Test Lines	11/14/2016	09:06:15	COM1	500 psi kickout test and 2500 psi pressure test
Event	7	Pump Spacer 1	Pump Spacer 1	11/14/2016	09:10:18	COM1	20 bbl water with dye in last 10
Event	8	Check Weight	Check weight	11/14/2016	09:23:43	COM1	13.5 ppg verified with pressurized scales
Event	9	Pump Lead Cement	Pump Lead Cement	11/14/2016	09:25:49	COM1	525 sks/163 bbl 13.5 ppg 1.74 ft3/sk 9.2 gal/sk
Event	10	Shutdown	Shutdown	11/14/2016	09:54:13	COM1	Washup on top of plug
Event	11	Drop Top Plug	Drop Top Plug	11/14/2016	09:56:54	COM1	
Event	12	Pump Displacement	Pump Displacement	11/14/2016	09:56:58	COM1	117 bbl water displacement
Event	13	Other	Cement to surface	11/14/2016	10:09:08	COM1	60 bbl into displacement. 30 bbl cement back total

Event	14	Bump Plug	Bump Plug	11/14/2016	10:18:41	COM1	600 psi final pump pressure. Pressured up to 1500 psi for casing pressure test
Event	15	Other	Check floats	11/14/2016	10:21:04	COM1	0.5 bbl back. Floats held
Event	16	Depart Location Safety Meeting	Depart Location Safety Meeting	11/14/2016	11:30:00	USER	

2.2 Custom Graph



