

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2017

Submitted Date:

04/14/2017

Document Number:

682402005**FIELD INSPECTION FORM**Loc ID: 330811 Inspector Name: Binschus, Chris On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448216	WELL	XX	10/31/2016		123-43802	BABCOCK 14C-33HZ	CI
448217	WELL	XX	10/31/2016		123-43803	BABCOCK 11N-33HZ	CI
448218	WELL	XX	10/31/2016		123-43804	BABCOCK 35C-33HZ	CI
448219	WELL	XX	10/31/2016		123-43805	BABCOCK 23N-33HZ	CI
448220	WELL	XX	10/31/2016		123-43806	BABCOCK 22N-33HZ	CI
448221	WELL	XX	10/31/2016		123-43807	BABCOCK 13E-33HZ	CI
448222	WELL	XX	10/31/2016		123-43808	BABCOCK 19N-33HZ	CI
448223	WELL	XX	10/31/2016		123-43809	BABCOCK 33C-33HZ	CI
448224	WELL	XX	10/31/2016		123-43810	BABCOCK 12N-33HZ	CI
448225	WELL	XX	10/31/2016		123-43811	BABCOCK 32N-33HZ	CI

General Comment:This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401247622.**Location Construction**Location ID: 330811 CDP: _____Comment: Topsoil stockpile has been stored and temporarily stabilized along the southern perimeter of location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____

Date: _____

Form 2A COAs:Comment: A disturbance area of 8.08 acres was mapped on 4/7/2017 using a Trimble Juno 3B handheld device.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date:**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs: Location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Other BMPs:

Corrective Action:

Date:

RETENTION PONDS	Yes		
-----------------	-----	--	--

Comments: Erosion BMPs: Two (2) sediment traps have been installed and IN-PROCESS of being completed (i.e., outlet still needs to be stabilized). Shallow groundwater has been encountered while constructing the western sediment trap.

Other BMPs:

Corrective Action: Operator needs to construct BMPs in such a manner that would not have direct impact to groundwater. Date: 04/28/2017

BERMS	Yes	Vehicle Trakcing	Yes`
-------	-----	------------------	------

Comments: Erosion BMPs: Location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Other BMPs:

Maintenance is needed on the vehicle tracking pad as some vehicle tracking evident on CR19.

Corrective Action:

Date:

Comment: BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

Corrective Action:**Date:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>448216</u>	Type: <u>WELL</u>	API Number: <u>123-43802</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448217</u>	Type: <u>WELL</u>	API Number: <u>123-43803</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448218</u>	Type: <u>WELL</u>	API Number: <u>123-43804</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448219</u>	Type: <u>WELL</u>	API Number: <u>123-43805</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448220</u>	Type: <u>WELL</u>	API Number: <u>123-43806</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448221</u>	Type: <u>WELL</u>	API Number: <u>123-43807</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448222</u>	Type: <u>WELL</u>	API Number: <u>123-43808</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448223</u>	Type: <u>WELL</u>	API Number: <u>123-43809</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448224</u>	Type: <u>WELL</u>	API Number: <u>123-43810</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>448225</u>	Type: <u>WELL</u>	API Number: <u>123-43811</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682402007.	binschusc	04/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682402007	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124239