

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2017

Submitted Date:

04/26/2017

Document Number:

680401411**FIELD INSPECTION FORM**

Loc ID 334481 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10310Name of Operator: FRAM OPERATING LLCAddress: 2313 LOGOS DRCity: GRAND JUNCTION State: CO Zip: 81505**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Mosnes, Arvid	970-260-7312	arvid.mosnes@framamericas.com	VP Operations
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291404	WELL	PR	05/13/2014	GW	077-09327	SIMINOE 32-2-J	WK

General Comment:

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291404	Type:	WELL	API Number:	077-09327	Status:	PR	Insp. Status:	WK
Workover									
Comment:	RACS drilling rigged up to pull tubing. Swab well. 4 swab runs made before rig mechanical failure. Approx. 4 1/2 bbls fluid returned. Operations to resume after rig repairs.								
Corrective Action:								Date:	