

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2017

Submitted Date:

05/03/2017

Document Number:

680601504**FIELD INSPECTION FORM**

Loc ID 325388 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 7650Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATIONAddress: 4900 COLLEGE BLVDCity: FARMINGTON State: NM Zip: 87402**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214687	WELL	PR	04/20/2005	GW	067-06291	LA POSTA CANYON 4	RI

General Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.

Inspected Facilities									
Facility ID:	214687	Type:	WELL	API Number:	067-06291	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within portions of the project area. Poor revegetation in the western portion of the project area.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ In _____	Production areas stabilized ? _____ In _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____
80% Revegetation _____	
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____ F _____	
Comment	<div style="border: 1px solid black; padding: 5px; color: blue;">Approximately 500 musk thistles were observed in the eastern and western portions and along the edges of the project area.</div>
Corrective Action	<div style="border: 1px solid black; padding: 5px; color: red;">Control weeds at the appropriate time but no later than June 15, 2017. If chemical control is used to treat weeds, then areas where desirable vegetation is damaged or killed, will need to be re-seeded.</div>
Date 06/15/2017	
Overall Interim Reclamation	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads Regraded _____	Contoured _____
Gravel removed _____	Culverts removed _____
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
Comment:	<div style="border: 1px solid black; height: 20px;"></div>
Corrective Action:	<div style="border: 1px solid black; height: 20px;"></div>
Date _____	

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Sediment is filling along wattles in the western portion of the project area. There is a portion of the western fill slope that has exposed soils, appears to be eroding, and stormwater controls are not in place. See attached photos.

Corrective Action: Erosion controls along the western edge of the fill slope need maintenance. Additional controls are needed along the slope where it is eroding. Successful revegetation of this area is the best way to stabilize. However, stormwater controls are needed for short-term stabilization.

Date: 06/16/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680601505	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138535