

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401277651
Date Received:
05/09/2017

FIR RESOLUTION FORM

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26580
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
Address: PO BOX 4289
City: FARMINGTON State: NM Zip: 87499
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Jennifer Dixon	701-264-4041	jennifer.a.dixon@conocophillips.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682501626
Inspection Date: 01/19/2017 FIR Submit Date: 01/20/2017 FIR Status: _____

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP Company Number: 26580
Address: PO BOX 4289
City: FARMINGTON State: NM Zip: 87499

LOCATION - Location ID: 436726

Location Name: Reserve 3-65 34-35 Number: 1H County: _____
Qtrqr: NENE Sec: 35 Twp: 3S Range: 65W Meridian: 6
Latitude: 39.752492 Longitude: -104.623217

FACILITY - API Number: 05-001-00 Facility ID: 436726

Facility Name: Reserve 3-65 34-35 Number: 1H
Qtrqr: NENE Sec: 35 Twp: 3S Range: 65W Meridian: 6
Latitude: 39.752492 Longitude: -104.623217

CORRECTIVE ACTIONS:

1 ☒ CA# 63063

Corrective Action: Perform interim reclamation on all areas not reasonably needed for production operations in accordance to reclamation rules. Reclaim interim areas to their original condition or final land use.

Date: 04/15/2017

Response: CA COMPLETED Date of Completion: 05/09/2017

Operator Comment: ConocoPhillips has reduced the pad size to ~2.90 acres (see attached as-built sketch).

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the Notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please find the attached document that outlines the work completed to reduce the pad size and repair BMPs for the Reserve 3-65 34-35 (Facility # 436726).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jennifer Dixon

Signed: _____

Title: Regulatory Coordinator

Date: 5/9/2017 7:01:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401277651	FIR RESOLUTION SUBMITTED
401277654	FIR Resolution Photos

Total Attach: 2 Files