

Landowner at 5403
CR 320 reports that
flowline was cut at
this access road

Reported original
alignment of 1"
yellow poly flowline
~1600 feet

Flowline
disconnected at
wellhead by
COGCC staff on
5/26/17

Bert Eaton #1

320

325

© 2016 Google

Google Earth