

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2017

Submitted Date:

06/05/2017

Document Number:

680301977

FIELD INSPECTION FORM

Loc ID 313907 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53790
Name of Operator: MARKUS PRODUCTION, INC
Address: 39 FAIRWAY LANE
City: LITTLETON State: CO Zip: 80123

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|---------------------------|---------|
| Brown, Mark | (720) 350-8858 | mark@markusproduction.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 227089 | WELL | PR | 03/26/2014 | OW | 087-07832 | WELKER 43-30 | PA |

General Comment:

[P&A in process](#)

Location

| | | | |
|--------------------|---|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Satisfactory Maintain lease road, begin reclamation process upon completion of P&A. | | |
| Corrective ActionL | | Date: | |

Overall Good:

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|--------------|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Satisfactory | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # 0 | | |
| Comment: | Remove all equipment upon completion of P&A, begin reclamation process. | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 227089 Type: WELL API Number: 087-07832 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: 970-522-3078

Surface Casing

Cement Volume (sx): 50+140

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): 5+25

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 6348,5500,1380,258

Cement Volume (sx): 5+25+50+140

Good Return During Job: YES

Cement Type: G

Comment: Well dead, pressure tested to 500 psi., RIH with tubing to 5687', loaded hole, pumped (25) sks cement for balance plug, displaced (30) bbls., POOH, rigged wire-line, shot/squeeze holes @ 1600', RIH with CICR, set retainer@1486', est. circulation, mixed/pumped (50) sks plug, 10.24 bbls cement (15.8#), displaced (6.5) bbls, stung out-pumped (2) bbls. on top. POOH, wireline shot squeeze holes @ 270', RIH to (140)', established circ.,mixed/pumped (140) sks cement (28.67) bbls of (15.8#) cement in returns. Shut in well - shut down for night.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | In Process | Other | In Process | | | |

Comment: [Continue stormwater erosion management BMP's until final reclamation approval from COGCC.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| P&A in process. No problems indicated | schureky | 06/05/2017 |