

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401259606  
Date Received:  
06/05/2017

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Scot Donato	303 398 0537	cogccinspections@gwogco.com
Tim Musgrave	970 460 1458	tmusgrave@gwogco.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684903352  
Inspection Date: 03/22/2017 FIR Submit Date: 03/22/2017 FIR Status:

Inspected Operator Information:

Company Name: GREAT WESTERN OPERATING COMPANY LLC Company Number: 10110  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 435635

Location Name: Spaur Brothers North Pad Number: 31-219HN County:  
Qtrqtr: NESE Sec: 31 Twp: 7N Range: 63W Meridian: 6  
Latitude: 40.529683 Longitude: -104.471103

FACILITY - API Number: 05-123-00 Facility ID: 435635

Facility Name: Spaur Brothers North Pad Number: 31-219HN  
Qtrqtr: NESE Sec: 31 Twp: 7N Range: 63W Meridian: 6  
Latitude: 40.529683 Longitude: -104.471103

CORRECTIVE ACTIONS:

1  CA# 68568

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 04/24/2017

Response: CA COMPLETED

Date of Completion: 05/19/2017

Operator Comment: Stained soil removed. Valves, pipes, fittings have been secured and/or repaired or replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**2**  CA# 68569

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 04/24/2017

Response: CA COMPLETED

Date of Completion: 05/19/2017

Operator Comment: Stained soil has been removed. Valves, pipes, fittings have been secured, and/or repaired or replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**3**  CA# 68570

Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.

Date: 04/03/2017

Response: CA COMPLETED

Date of Completion: 05/19/2017

Operator Comment: Weeds have been removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**4**  CA# 68571

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d.

Date: 04/24/2017

Response: CA COMPLETED

Date of Completion: 05/19/2017

Operator Comment: Stained soil has been removed. Valves, pipes, fittings have been secured and/or repair or replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Laura Harter

Signed: \_\_\_\_\_

Title: Production Tech

Date: 6/5/2017 2:53:47 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401259606	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files