

REMEDIAL WORK PLAN SG 922-32D								
API	Well Name	Well Type	Producing/Injection Zone	Depth, Top Of Cement	Depth, Top of Middle WFRK	Depth, Top Williams Fork Producing Zone	Remediation Required	Comment
05045172000000	SG 431-32	Gas	WFRK PROD	4652	3311	3828	*YES	
05045185330000	SG 914 32D	INJ	RLNS/CZZT/CRCN INJ	3900	3215	NA	*YES	
05045230230000	SG 924-29D	INJ	CZZT/CRCN INJ	3577	3645	NA	*MAYBE	
05045226540000	SG 922-32D	INJ	CZZT/CRCN INJ	2226	3055	NA	No	
05045171990000	SG 441-32	Gas	WFRK PROD	2168	3622	4065	No	
05045179160000	SG 432-32	Gas	WFRK PROD	2064	3201	3894	No	
05045179750000	SG 522-32	Gas	WFRK PROD	1466	3074	3694	No	
05045184410000	SG 44-32	Gas	WFRK PROD	1064	3304	3927	No	
05045184400000	SG 433-32	Gas	WFRK PROD	960	3025	3668	No	
05045184420000	SG 334-32	Gas	WFRK PROD CZZT/CRN INJ	860	3009	3887	No	

TEP has reviewed wells within a half mile and has identified there mabe wells that require remedial or corrective repairs