

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

06/15/2017

Document Number:

684903847

### FIELD INSPECTION FORM

Loc ID 439315 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
 Name of Operator: PDC ENERGY INC  
 Address: 1775 SHERMAN STREET - STE 3000  
 City: DENVER State: CO Zip: 80203

**Findings:**

- 2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439316	WELL	PR	02/21/2016	OW	123-40373	Honebein 7K-243	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 439316 Type: WELL API Number: 123-40373 Status: PR Insp. Status: PR

**Complaint**

Comment: [Complaint #: 200442989](#)  
 Field Inspector Assigned: C Pesicka  
 Well Number: 05- Location #: 439315  
 Inspection Document #: 684903847  
 Nature of complaint: Sound  
 If Sound GPS Coordinates of Survey Location:  
 Inspection Observations:  
 Compressor unit was not running again. Spoke with pumper on location who stated that the compressor was being swapped out. Contacted PDC area production foreman who confirmed that the compressor unit would be replaced by Monday (06/19/17). Furthermore, was informed that if the complainant still had issues with sound, PDC would take steps to mitigate the sound via a sound wall.

Corrective Action:

Date: