

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401270356

Date Received:

04/28/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601151  
Inspection Date: 12/06/2016 FIR Submit Date: 12/14/2016 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326100

Location Name: MEDIAN,PRESENTACION Number: 11SWSE County: LA PLATA  
GAS UT A-N33N10  
Qtrqr: SWSE Sec: 11 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.113880 Longitude: -107.900146

FACILITY - API Number: 05-067-00 Facility ID: 215866

Facility Name: PRESENTACION MEDINA A Number: 1  
Qtrqr: SWSE Sec: 11 Twp: 33N Range: 10W Meridian: N  
Latitude: 37.113880 Longitude: -107.900146

CORRECTIVE ACTIIONS:

1  CA# 54564

Corrective Action: Conduct interim reclamation on well pad areas not needed for production operations. Date: 05/01/2017

Response: CA COMPLETED Date of Completion: 04/18/2017

Operator Comment: BP completed on 4/18/17 addressing erosion comment and reducing pad size to comply with at or below 0.81 acres per LaPlata County Code by performing the following (see attached photos):  
Grading/recontour  
Seeding  
Erosion Repairs

Install Rock Run Down  
Repaired Berm  
Grading of Well Pad  
Shrunk the location's footprint size and seeded it.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: BP completed on 4/18/17 addressing erosion comment and reducing pad size to comply with at or below 0.81 acres per LaPlata County Code by performing the following (see attached photos):  
Grading/recontour  
Seeding  
Erosion Repairs  
Install Rock Run Down  
Repaired Berm  
Grading of Well Pad  
Shrunk the location's footprint size and seeded it.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 4/28/2017 7:31:38 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401270356	FIR RESOLUTION SUBMITTED
401270357	Photos of work completed

Total Attach: 2 Files