

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401299644
Date Received:
06/04/2017

FIR RESOLUTION FORM

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601473
Inspection Date: 04/14/2017 FIR Submit Date: 04/27/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325774

Location Name: BARNES GAS UNIT A-N33N9W Number: 2NESE County: LA PLATA
Qtrqr: NESE Sec: 2 Twp: 33N Range: 9W Meridian: N
Latitude: 37.130858 Longitude: -107.790917

FACILITY - API Number: 05-067-00 Facility ID: 215361

Facility Name: BARNES A Number: 1
Qtrqr: NESE Sec: 2 Twp: 33N Range: 9W Meridian: N
Latitude: 37.130858 Longitude: -107.790917

CORRECTIVE ACTIIONS:

1 CA# 71328

Corrective Action: Remove debris and reclaim, or provide a signed surface owner waiver letter taking responsibility for portions of the project area that they are utilizing. See comments below for additional detail.

Date: 06/30/2017

Response: CA COMPLETED Date of Completion: 05/18/2017

Operator Comment: BP has performed the following work on this location see attached photos
Erosion Repairs
Install Rock Run Down

Clean up Operator Debris
Clean Up Land Owner Debris
Grading of Well Pad
Removed sediment from BMP's

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 71329

Corrective Action: Control weeds at the appropriate time but no later than June 15, 2017.

Date: 06/15/2017

Response: CA COMPLETED

Date of Completion: 05/15/2017

Operator
Comment:

Weeds previously addressed on FIR document#401282644

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 71330

Corrective Action: Stormwater controls need to be installed to stabilize erosional channel on the southern edge of the project area.

Date: 05/31/2017

Response: CA COMPLETED

Date of Completion: 05/18/2017

Operator
Comment:

BP has performed the following work on this location see attached photos
Erosion Repairs
Install Rock Run Down
Clean up Operator Debris
Clean Up Land Owner Debris
Grading of Well Pad
Removed sediment from BMP's

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has performed the following work on this location see attached photos
Erosion Repairs
Install Rock Run Down
Clean up Operator Debris
Clean Up Land Owner Debris
Grading of Well Pad
Removed sediment from BMP's
Weed CA previously addressed on FIR doc#401282644

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 6/4/2017 7:30:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401299644	FIR RESOLUTION SUBMITTED
-----------	--------------------------

