

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401299648
Date Received:
06/04/2017

FIR RESOLUTION FORM

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Labowskie, Steve		steve.labowskie@state.co.us
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685302760
Inspection Date: 04/21/2017 FIR Submit Date: 04/24/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326388

Location Name: C.V. THOMPSON ET UX G. Number: 28SWNW County: LA PLATA
U.-M34N7W
Qtrqtr: SWN Sec: 28 Twp: 34N Range: 7W Meridian: M
W
Latitude: 37.165584 Longitude: -107.619885

FACILITY - API Number: 05-067-00 Facility ID: 216355

Facility Name: CV THOMPSON Number: 1
Qtrqtr: SWN Sec: 28 Twp: 34N Range: 7W Meridian: M
W
Latitude: 37.165584 Longitude: -107.619885

CORRECTIVE ACTIIONS:

1 CA# 71116

Corrective Action: Clean up and remediate stained soil to comply with Rule 906.a. Date: 01/30/2017

Response: CA COMPLETED Date of Completion: 05/20/2017

stained soils have been cleaned up see attached photos

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

2 CA# 71117

Corrective Action: Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for futher details.

Date: 01/30/2017

Response: CA COMPLETED

Date of Completion: 05/20/2017

Operator Comment: Unused equipment has been removed from location

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

3 CA# 71118

Corrective Action: Repair or replace and securely fasten valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical conditionper Rule 605.d.

Date: 05/25/2017

Response: CA COMPLETED

Date of Completion: 05/20/2017

Operator Comment: Operations has performed maintenance on equipment valves, pipes and fittings

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

4 CA# 71119

Corrective Action: Install required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 01/30/2017

Response: CA COMPLETED

Date of Completion: 05/20/2017

Operator Comment: Rock rundowns have been installed to control erosion and storm water

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: BP has completed all CA's on inspection see attached documentation

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401299648	FIR RESOLUTION SUBMITTED
401299649	Storm water and debris closure photos
401299650	Secondary containment photos

Total Attach: 3 Files