

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401331775
Date Received:
07/05/2017

FIR RESOLUTION FORM

CA Summary:
2 of 5 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10630
Name of Operator: ALTA MESA SERVICES LP
Address: 15021 KATY FREEWAY SUITE 400
City: HOUSTON State: TX Zip: 77094
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
JAMESON MAX	281-944-0638	mjameson@altamesa.net
Housey, Melissa		melissa.housey@state.co.us
JOHNSON JERRY	361-230-5151	jjohnson@altamesa.net
KASSAB DIANE		dkassab@altamesa.net
Adamczyk, Megan		megan.adamczyk@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504439
Inspection Date: 06/12/2017 FIR Submit Date: 06/13/2017 FIR Status:

Inspected Operator Information:

Company Name: ALTA MESA SERVICES LP Company Number: 10630
Address: 15021 KATY FREEWAY SUITE 400
City: HOUSTON State: TX Zip: 77094

LOCATION - Location ID: 429618

Location Name: Freeman Number: 3-24 County: HUERFANO
Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6
W
Latitude: 37.684828 Longitude: -105.067631

FACILITY - API Number: 05-055-00 Facility ID: 429619

Facility Name: Freeman Number: 3-24
Qtrqr: NWS Sec: 24 Twp: 27S Range: 69W Meridian: 6
W
Latitude: 37.684828 Longitude: -105.067631

CORRECTIVE ACTIONS:

1 CA# 81622

Corrective Action: Comply with Rule 603.f. Remove unused equipment.

Date: 06/22/2017

Response: CA COMPLETED

Date of Completion: 07/05/2017

Operator Comment: 1. A Sundry Notice Form 4 (Document No. 401331736) was submitted on 7/05/2017 to request delayed interim reclamation. The reclamation will be performed after the completion activities are finished as detailed on the Form 4.

2. The unused equipment are the components of the temporary land tank that needs to be assembled to contain the frac water. It will be erected once a minimum volume of water is supplied to hold the plastic liner in place and build the metal outer wall around it.

COGCC Decision: Approved

COGCC Representative: Comment 1 does not apply.
 Comment 2 applies to the corrective action. It appears that the equipment identified by the inspection will be used as indicated by the comment.

4 CA# 81625

Corrective Action: Perform Interim reclamation and reduce the size of the location as specified in the 2A.

Date: 06/12/2014

Response: CA COMPLETED

Date of Completion: 07/05/2017

Operator Comment: A Sundry Notice Form 4 (Document No. 401331736) was submitted on 7/05/2017 to request delayed interim reclamation. The reclamation will be performed after the completion activities are finished as detailed on the Form 4.

COGCC Decision: **Not Approved**

COGCC Representative: Email correspondence was sent to the operator on 7/5/2017 regarding the NTO for delayed Interim Reclamation. The Form 4 document number 401331736 request for delayed interim reclamation is incomplete. The operator has not submitted the required documentation which is described in the NTO. The corrective action remains until the required documentation has been submitted.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA# 81623 and CA# 81626 have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Max Jameson

Signed: _____

Title: Regulatory Coordinator

Date: 7/5/2017 9:39:30 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401331775	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files