

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401330288
Date Received:
07/03/2017

FIR RESOLUTION FORM

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95750
Name of Operator: WESTERN INTERIOR ENERGY INC
Address: P O BOX 247
City: CRESTED BUTTE State: CO Zip: 81224
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Grogg, Cindy	970-349-5885	wiedmo@msn.com
TRUETTNER JIM	970-349-5883	wiewjt@msn.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504350
Inspection Date: 06/01/2017 FIR Submit Date: 06/01/2017 FIR Status:

Inspected Operator Information:

Company Name: WESTERN INTERIOR ENERGY INC Company Number: 95750
Address: P O BOX 247
City: CRESTED BUTTE State: CO Zip: 81224

LOCATION - Location ID: 319953

Location Name: HILTON-63S62W Number: 18SESE County: ADAMS
Qtrqtr: SESE Sec: 18 Twp: 3S Range: 62W Meridian: 6
Latitude: 39.784049 Longitude: -104.360626

FACILITY - API Number: 05-001-00 Facility ID: 201989

Facility Name: HILTON Number: 1
Qtrqtr: SESE Sec: 18 Twp: 3S Range: 62W Meridian: 6
Latitude: 39.784049 Longitude: -104.360626

CORRECTIVE ACTIONS:

1 CA# 79090

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the phase II of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all riser Risers/ Flowlines/ Pipelines . Date: 06/30/2017

Response: CA COMPLETED Date of Completion: 07/03/2017

Operator Comment: adding attachment. Contract between Western and IREA to remove the electric pole.

COGCC Decision: **Not Approved**

COGCC Representative: The pipe riser is located at the tank battery site associated with the HILTON 1 well site. Aerial imagery indicates the tank battery site was in use up until the Hilton 1 well was plugged and abandoned in 2013. The pipe riser must be removed to Comply with Rule 1004.

2 CA# 79091

Corrective Action: All Risers/ Flowlines/ Pipelines must abide by the Phase I of the May 2, 2017 Flowline NTO. Respond when corrective action is complete with date completed and photos attached to an FIRR response to CA. Make sure to identify both endpoints of all Risers/ Flowlines/ Pipelines.

Date: 05/31/2017

Response: CA COMPLETED

Date of Completion: 07/03/2017

Operator Comment: attachment. Contract from IREA to remove electric pole

COGCC Decision: **Not Approved**

COGCC Representative: The pipe riser is located at the tank battery site associated with the HILTON 1 well site. Aerial imagery indicates the tank battery site was in use up until the Hilton 1 well was plugged and abandoned in 2013. The pipe riser must be removed to Comply with Rule 1004.

3 CA# 79092

Corrective Action: Fill in area of subsidence at the tank battery site. Remove the powerline that runs from the location to the nearest point of usage.

Date: 06/30/2017

Response: CA COMPLETED

Date of Completion: 07/03/2017

Operator Comment: Attachment: Contract to remove electric pole

COGCC Decision: Approved pending re-inspection

COGCC Representative: The tank battery site was associated with the HILTON 1 well site. Aerial imagery indicates the tank battery site was in use up until the Hilton 1 well was plugged and abandoned in 2013. The area of subsidence must be filled in to Comply with Rule 1004. Documentation was provided regarding removal of electric utilities. See doc #401327067

OPERATOR COMMENT AND SUBMITTAL

Comment: This is an addendum to original CA submitted in June

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cindy Grogg

Signed: _____

Title: Office Manager

Date: 7/3/2017 8:33:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401330288	FIR RESOLUTION SUBMITTED
401330289	Contract between Western and IREA

Total Attach: 2 Files