

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401341079

Date Received:

07/13/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705

Name of Operator: WPX ENERGY PRODUCTION LLC

Address: P O BOX 3102 MS-25-2

City: TULSA State: OK Zip: 74101

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lacey Granillo</u>	<u>505-333-1816</u>	<u>lacey.granillo@wpxenergy.com</u>
<u>Darren Rowley</u>	<u>505-947-4974</u>	<u>darren.rowley@wpxenergy.com</u>
<u>Deborah Watson</u>	<u>505-333-1880</u>	<u>deborah.watson@wpxenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601750

Inspection Date: 07/10/2017

FIR Submit Date: 07/11/2017

FIR Status: _____

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC

Company Number: 96705

Address: P O BOX 3102 MS-25-2

City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 326593

Location Name: BONDAD 33-10-N33N10W Number: 11NWNE County: LA PLATA

Qtrqtr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N

Latitude: 37.121690 Longitude: -107.901720

FACILITY - API Number: 05-067-00 Facility ID: 258550

Facility Name: BONDAD 33-10 Number: 5A

Qtrqtr: NWNE Sec: 11 Twp: 33N Range: 10W Meridian: N

Latitude: 37.121690 Longitude: -107.901720

CORRECTIVE ACTIONS:

1 CA# 85737

Corrective Action: Additional stormwater controls need to be installed in the southeastern portion of the project area where there is little vegetation and erosion is occurring, as well as the southeastern well pad diversion. Seeding of exposed soils is recommended during the fall 2017 seeding window to help stabilize eroding areas. The portion of the northeastern fill slope that is eroding needs stabilization and sediment controls in the roadside drainage where sediment is being deposited and transported.

Date: 08/11/2017

Response: CA COMPLETED

Date of Completion: 07/12/2017

Operator Comment: On July 12, 2017, a crew reseeded and mulched areas identified above. Additional stormwater controls were installed on July 12, 2017. See attached photos.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: _____

Title: Environmental Specialist

Date: 7/13/2017 1:55:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401341097	Photo 1
401341099	Photo 2
401341101	Photo 3
401341103	Photo 4
401341105	Photo 5
401341106	Photo 6
401341107	Photo 7
401341109	Photo 8

Total Attach: 8 Files