

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401343346  
Date Received:  
07/17/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		<a href="mailto:SanJuanCOGCC@bp.com">SanJuanCOGCC@bp.com</a> <a href="mailto:Sabre.Beebe@bp.com">Sabre.Beebe@bp.com</a>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680601600  
Inspection Date: 05/05/2017 FIR Submit Date: 06/05/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 325501

Location Name: SHOEMAKER-N35N8W Number: 34NWSE County: LA PLATA  
Qtrqr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.255727 Longitude: -107.728732

### FACILITY - API Number: 05-067- -00 Facility ID: 214901

Facility Name: SHOEMAKER Number: 01-34 1  
Qtrqr: NWSE Sec: 34 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.255727 Longitude: -107.728732

### CORRECTIVE ACTIONS:

2 ☒ CA# 80340

Corrective Action: Repair northern diversion and apply stormwater controls to de-energize flows and reduce sediment flows.

Date: 07/07/2017

Response: CA COMPLETED

Date of Completion: 07/10/2017

Operator Comment: Storm water BMP repairs have been performed on location. Repairs have been made to erosion channels, repairs have been made to the location berm and wattles have been installed to prevent sediment flow and to slow down storm waters. See attached documentation.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Storm water CA has been addressed as of 7/10/17 with repairs to erosion channels, berms and wattle installation. See attached photo

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 7/17/2017 9:56:14 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401343346	FIR RESOLUTION SUBMITTED
401343351	Storm water BMP CA closure photos

Total Attach: 2 Files