



Fwd: COGCC FIELD INSPECTION REPORT [Doc#689800143, Loc Id: 316782 Name: WOLF MOUNTAIN-67N87W 15SWNE] SUBMITTED NOTICE

1 message

Fischer - DNR, Alex <alex.fischer@state.co.us>
To: OGCC EnviroScan - DNR <dnr_ogcc.enviroscan@state.co.us>

Mon, Aug 14, 2017 at 6:48 AM

Scanning Work Request:

Please upload this emnail as follows:

Document Name(s)	1. Operator's August 11,2017 email Correspondence	
Document Number	<i>(leave blank if not already assigned)</i>	
Date Received	8/11/2017	
Is data entry needed?	NO	
Indexing Information	Unique ID Type	Unique ID Number
First	Location ID	316782
Second		
Third*		
Additional Instructions		

Thanks!

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

----- Forwarded message -----

From: **Ann Miller** <ann@energy-investments.com>

Date: Fri, Aug 11, 2017 at 5:20 PM

Subject: RE: COGCC FIELD INSPECTION REPORT [Doc#689800143, Loc Id: 316782 Name: WOLF MOUNTAIN-67N87W 15SWNE] SUBMITTED NOTICE

To: "Fischer - DNR, Alex" <alex.fischer@state.co.us>

Cc: Kris Neidel - DNR <kris.neidel@state.co.us>, "Waldron - DNR, Emily" <emily.waldron@state.co.us>, Jeremy Ferrin - DNR <jeremy.ferrin@state.co.us>, Dapco3@aol.com, Booco's <boocosinc@aol.com>, Kristine Peterson <k.peterson@laramidegeo.com>, energyinv@msn.com

Energy Investments, Inc. ("EII") would like to respond to the Field Inspection Report dated 8/10/17, document #689800143.

Report Comment: [Stained soil at wellhead. Some of it has been covered by fresh gravel, some staining is fresh and ongoing.](#)

Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)

EII Response: A spill occurred and was discovered August 1, 2017. It was cleaned upon discovery. The spill was limited to approximately 77 gallons and contained within a 10 square foot radius of the wellhead. A preliminary spill report has been filed with COGCC. Our pumper reports that there is not an ongoing leak.

Report Comment: [1 2" steel riser observed at wellhead not marked for abandonment, not locked out tagged out.](#)

Corrective Action: [Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance documents can provide further details. Contact \[dnr_cogccengineering@state.co.us\]\(mailto:dnr_cogccengineering@state.co.us\) with resolution plan.](#)

EII Response: Our pumper has taken care of this riser. Details of the corrective action will be provided as soon as possible.

Report Comment: [Gas being vented or flared during non-upset condition without prior approval from COGCC. Well pumping and ECD/flare is not lit.](#)

Corrective Action: [Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.](#)

EII Response: The well has been permitted to flare and has undergone APEN testing, meeting and exceeding requirements. The flare had been knocked over by wildlife (Elk) in the vicinity and was corrected and re-lit immediately upon discovery.

Report Comment: [Lube oils stored at wellhead and on pumpjack base with no secondary containment/covering.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f. guidance document for further details.](#)

EII Response: Secondary containment will be installed for the lube oils stored at the wellhead.

Thank you,

Ann Miller

Business Manager



PO Box 17630

Golden, CO 80402

303-912-2188 (direct)

ann@energy-investments.com

www.energy-investments.com

From: Stephen Chamberlain [mailto:energyinv@msn.com]

Sent: Thursday, August 10, 2017 4:12 PM

To: Fischer - DNR, Alex

Cc: Kris Neidel - DNR; Waldron - DNR, Emily; Jeremy Ferrin - DNR; Dapco3@aol.com; 'Booco's'; Ann Miller; Kristine Peterson

Subject: RE: COGCC FIELD INSPECTION REPORT [Doc#689800143, Loc Id: 316782 Name: WOLF MOUNTAIN-67N87W 15SWNE] SUBMITTED NOTICE

Dear Alex, Thank you for your email. I spoke with my pumper on Monday who indicated we do NOT have an ongoing leak. However, I will look into it further today and get back to you.

Best regards,

Stephen P. Chamberlain

President



PO Box 17630

Golden, CO 80401

303.249.7948

303.526.0871

www.energy-investments.com

From: Fischer - DNR, Alex [<mailto:alex.fischer@state.co.us>]

Sent: Thursday, August 10, 2017 3:33 PM

To: Stephen Chamberlain <energyinv@msn.com>

Cc: Kris Neidel - DNR <kris.neidel@state.co.us>; Waldron - DNR, Emily <emily.waldron@state.co.us>; Jeremy Ferrin - DNR <jeremy.ferrin@state.co.us>

Subject: Fwd: COGCC FIELD INSPECTION REPORT [Doc#689800143, Loc Id: 316782 Name: WOLF MOUNTAIN-67N87W 15SWNE] SUBMITTED NOTICE

Mr. Chamberlain,

From the attached Inspection, it appears the well has an ongoing leak. Immediately stop the leak and contact Kris Neidel via phone and email and myself via email when this has been done.

Since COGCC has witnessed what appears to be an ongoing Spill/Release and has notified you via the Inspection and email, per Rule, ENERGY INVESTMENTS INC, shall submit an Initial Spill/Release Form 19 within 72 hours.

Alex

----- Forwarded message -----

From: **COGCC Field Inspection Report** <emily.waldron@state.co.us>

Date: Thu, Aug 10, 2017 at 3:00 PM

Subject: COGCC FIELD INSPECTION REPORT [Doc#689800143, Loc Id: 316782 Name: WOLF MOUNTAIN-67N87W 15SWNE] SUBMITTED NOTICE

To: dnr_cogccenforcement@state.co.us, energyinv@msn.com, dnr_cogcc_Engineering@state.co.us, kris.neidel@state.co.us, mike.leonard@state.co.us, alex.fischer@state.co.us

Cc: emily.waldron@state.co.us



Colorado
Oil & Gas Conservation
Commission
Department of Natural Resources

1120 Lincoln St. Suite 801
Denver, CO 80203

Phone: (303) 894-2100

FAX: (303) 894-2109

cogcc.state.co.us

COGCC Field Inspection Report

ATTACHED REPORT HAS BEEN SUBMITTED TO COGCC DATABASE BASED ON FIELD INSPECTION RESULTS. OPERATORS HAVE SEVEN (7) DAYS TO REVIEW BEFORE THE INSPECTION FORM IS POSTED TO THE WEBSITE.

PLEASE REVIEW ENTIRE REPORT. **COMMENTS** ARE HIGHLIGHTED IN **BLUE**, **CORRECTIVE ACTION ITEMS** ARE HIGHLIGHTED IN **RED**.

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

| alex.fischer@state.co.us www.colorado.gov/cogcc

--

Alex Fischer, P.G.

Environmental Supervisor, Western Colorado



P 303.894.2100 x5138 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

