

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2017

Submitted Date:

08/14/2017

Document Number:

666803481**FIELD INSPECTION FORM**Loc ID 335234 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Couts, Brandon		bcoutts@mustangresourcesllc.com	Field Operations
Smith, Matt		msmith@mustangresourcesllc.com	
Austin, Chris	970-756-1696	caustin@mustangresourcesllc.com	
Leonard, Mike		mike.leonard@state.co.us	
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210799	WELL	PR	04/24/2014	GW	045-06557	MEAD 24-14MV-6S-94W	PR
210812	WELL	PR	12/01/2016	GW	045-06570	MEAD 24-14W-6S-94W	PR

General Comment:

Entering location observed gas venting out pressure relief valve on top of produced water tank. Called pumper at 12:59 pm no answer left message. Called 1-888-291-8588 number listed on tank as 24 hour emergency contact at 1:07 pm. No answer left message. Attempted to call pumper again at 1:08, 1:17 and left messages. Attempted to call 1-888-291-8588 number 1:12, 1:22 and left messages. I called my supervisor at 1:28 pm and informed of the situation. He informed me to call Garfield County Non emergency line and inform them that well was venting and we were on location and he would start making his phone calls. At 1:37 Garfield County oil and gas liaison called and left message that he had reached a Mustang company Representative and that they were sending someone out. At 2:27 I was contacted by a Mustang company Representative and was informed they were sending a employee from Craig Colorado with estimated time of arrival of 1 -1/2 hours. He asked me if I could shut well in using the master valve. Called supervisor to see if that was possible, response was go ahead if You are good doing so. I shut the well in at 2:50.

LocationOverall Good: ☒**Signs/Marker:**

Type TANK LABELS/PLACARDS

Comment: Action require item noted in previous inspection doument number 666802322 dated 6/30/2016 have not been satisfied

Previous Inspection comment, 90 bbls tank need Placard and tank lables.
Corrective Action listed Install sign to comply with rule 210.

Corrective Action: Corrective action date has expired,

Date: 07/21/2016

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Chemical unit at wellhead

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		39.506931,-107.841967
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:		Centralized battery				
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	YES					
Comment:	Well venting thru pressure relief valve on produced water tank					
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 210799 Type: WELL API Number: 045-06557 Status: PR Insp. Status: PR**Producing Well**Comment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 210812 Type: WELL API Number: 045-06570 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing](#)

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401375380	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226349
666803486	Mustang	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4226339