

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/17/2017

Submitted Date:

08/22/2017

Document Number:

689800191

**FIELD INSPECTION FORM**

Loc ID 312764 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 68710  
Name of Operator: PETERSON ENERGY OPERATING INC  
Address: 2154 W EISENHOWER BLVD  
City: LOVELAND State: CO Zip: 80537

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
peterson, andy	970-669-7411	andy.peterson@petersonenergy.com	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222239	WELL	PR	01/28/2015	OW	081-05201	KNOWLTON 5	PR

**General Comment:**

*(This area is currently blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	1 - 2" steel riser observed at 40.33135, -107.60483 not in use and not marked for abandonment or locked out tagged out.		
Corrective Action:	"Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details. Contact dnr_cogccengineering@state.co.us with resolution plan."		Date: <u>09/05/2017</u>
Type: Deadman # & Marked	# 4		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		40.331260,-107.604830
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 222239 Type: WELL API Number: 081-05201 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Pumping.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689800192	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4233987">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4233987</a>