

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401385747  
Date Received:  
08/24/2017

FIR RESOLUTION FORM

CA Summary:  
2 of 2 CAs from the FIR responded to on this Form  
2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Harrison, Lyndon		lyndon_harrison@xtoenergy.com
Trujillo, Irwin	719-846-0272/719-859-2264	irwin_trujillo@xtoenergy.com
Fitzgerald, Edie	719-845-2108/719-859-1394	Edie_Fitzgerald@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900036  
Inspection Date: 07/21/2017 FIR Submit Date: 07/24/2017 FIR Status:

Inspected Operator Information:

Company Name: XTO ENERGY INC Company Number: 100264  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

LOCATION - Location ID: 307278

Location Name: APACHE CANYON-634S68W Number: 12SESW County: LAS ANIMAS  
Qtrqtr: SESW Sec: 12 Twp: 34S Range: 68W Meridian: 6  
Latitude: 37.093930 Longitude: -104.946890

FACILITY - API Number: 05-071- -00 Facility ID: 217352

Facility Name: APACHE CANYON Number: 12-14  
Qtrqtr: SESW Sec: 12 Twp: 34S Range: 68W Meridian: 6  
Latitude: 37.093930 Longitude: -104.946890

CORRECTIVE ACTIONS:

1  CA# 87587

Corrective Action: Clean up oil from engine skid and fix leak. Date: 08/07/2017

Response: CA COMPLETED Date of Completion: 08/02/2017

Operator Comment: No active leak was present. The skid of the liquid ring compressor was cleaned and the oil removed.

COGCC Decision: Approved

COGCC  
Representative:

**2**  CA# 87588

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/28/2017

Response: CA COMPLETED

Date of Completion: 08/23/2017

Operator Comment: Installed road base and crowned the driving surface to create sheet flow. Dominated the bar ditch to receive runoff. Installed (2) water turnouts to allow the roadway surface to drain.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The lube oil was removed and the skid was washed on 8/02/17. The roadway improvements were completed on 08/23/17.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: \_\_\_\_\_

Title: Sr. Environmental Tech.

Date: 8/24/2017 10:19:06 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401385747	FIR RESOLUTION SUBMITTED
401385791	Liquid ring compressor skid was cleaned
401385796	Roadway improvements

Total Attach: 3 Files