

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401394386

Date Received:  
09/05/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10330

Name of Operator: INVESTMENT EQUIPMENT LLC

Address: 412 W PLATTE AVE

City: FT MORGAN State: CO Zip: 80701

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Rebol, David

(970) 867-9007

daverebol@hotmail.com

Young, Rob

rob.young@state.co.us

Highberger, Kathryn

(970) 867-9007

dkama@kci.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 688300026

Inspection Date: 08/18/2017

FIR Submit Date: 08/18/2017

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: INVESTMENT EQUIPMENT LLC

Company Number: 10330

Address: 412 W PLATTE AVE

City: FT MORGAN State: CO Zip: 80701

LOCATION - Location ID: 316934

Location Name: COLORADO STATE-63S53W Number: 36NWNW County: WASHINGTON

Qtrqr: NWN Sec: 36 Twp: 3S Range: 53W Meridian: 6

W

Latitude: 39.753083 Longitude: -103.271594

FACILITY - API Number: 05-121- -00 Facility ID: 233291

Facility Name: COLORADO STATE Number: 1

Qtrqr: NWN Sec: 36 Twp: 3S Range: 53W Meridian: 6

W

Latitude: 39.753083 Longitude: -103.271594

CORRECTIVE ACTIONS:

1 CA# 93330

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 09/20/2017

Response: CA COMPLETED

Date of Completion: 09/01/2017

Extra dirt hauled in to build up berms

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

**2** CA# 93331

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 09/20/2017

Response: CA COMPLETED

Date of Completion: 09/01/2017

Operator  
Comment:

Cleaned out siphon leg of tank. Cleaned up stained soil.

COGCC Decision:

COGCC  
Representative:

**3** CA# 93332

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 09/20/2017

Response: CA COMPLETED

Date of Completion: 09/01/2017

Operator  
Comment:

Extra dirt hauled in to build up berms.

COGCC Decision:

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: This work resolves all 3 CA's required.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jim Chisholm

Signed: \_\_\_\_\_

Title: Managing Member

Date: 9/5/2017 8:53:45 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401394411	Photos of completed corrective work
-----------	-------------------------------------

Total Attach: 1 Files