

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2017

Submitted Date:

09/24/2017

Document Number:

688300328

**FIELD INSPECTION FORM**

Loc ID 432416 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 19160  
Name of Operator: CONOCO PHILLIPS COMPANY  
Address: P O BOX 2197  
City: HOUSTON State: TX Zip: 77252-

**Findings:**

8 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Aldrich, Brian	307-240-1882	Brian.C.aldrich@conocophillips.com	Production
Prasanna, Sonu	832-486-2299	sonu.prasanna@conocophillips.com	Regulatory Supervisor
Gahr, Dean	(303) 268-3723	Dean.P.Gahr@conocophillips.com	All DJ Basin Inspections
Dixon, Jennifer	(701) 264-2041	jennifer.a.dixon@conocophillips.com	Regulatory Coordinator
Strickler, Robert		Robert.D.Strickler@conocophillips.com	All DJ Basin Inspections
Westerdale, Barbara		barbara.westerdale@state.co.us	COGCC Permitting

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432441	WELL	XX	07/14/2015	LO	005-07206	Tebo 28-27 1H	UN
450159	WELL	XX	04/28/2017		005-07272	Tebo 4-64 28-27 2H_D	AL

**General Comment:**

Contact Barbara Westerdale/COGCC permitting on status of these two wells. One appears to be an AL (T-post stake next to fenced well). Fenced well appears to have conductor and surface casing set. See attached photos.

**Inspected Facilities**

Facility ID: 432441 Type: WELL API Number: 005-07206 Status: XX Insp. Status: UN

Facility ID: 450159 Type: WELL API Number: 005-07272 Status: XX Insp. Status: AL

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps	Fail			
Compaction	Pass	Compaction	Pass			

Comment: [See attached photos of full sediment traps on road going down hill to well just past gate. Talked to operator and they will be cleaned out.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/24/2017

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401413345	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4259408">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4259408</a>
688300345	Conoco Tebo 28-27 and 4-64 28-27	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4259372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4259372</a>