

Location			
Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	OK		
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b.		Date: 10/26/2017
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	PIPE BY PUMP JACK		
Corrective Action:	Comply with Rule 603.f .		Date: 10/26/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	>= 5 bbls	
Comment:	SOILEE DIRT AROUND MOTOR MOUNTRS		
Corrective Action:	Remove free fluids and contact COGCC EPS staff per Rule 906.b.		Date: 10/26/2017
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:	INTERMITTER CONTROLLER ON WELLHEAD		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	PUMP JACK NOT IN USE		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203512 Type: WELL API Number: 001-09072 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: OK

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401413920	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260060
685503999	WELL SIGN, UNUSED PIPE, SOILED DIRT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4260054