

- IGE 132 05-067-09615



Photo 1: Wellhead sign.

- IGE 132 05-067-09615



Photo 2: Steel cable.

- IGE 132 05-067-09615



Photo 3: Steel cable 2.

- IGE 132 05-067-09615



Photo 4: Thread protectors.

- IGE 132 05-067-09615



Photo 5: Pallet at gas meter shed.

- IGE 132 05-067-09615



Photo 6: Newly drilled wellhead.

- IGE 132 05-067-09615



Photo 7: Location overview.

- IGE 132 05-067-09615



Photo 8: Location overview 2.