

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/13/2017

Submitted Date:

10/13/2017

Document Number:

684904600**FIELD INSPECTION FORM**Loc ID 331082 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		pgallagh@blm.gov	BLM; federal/federal inspections
,		vkoehler@fs.fed.us	USFS; federal/federal inspections
,		regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258301	WELL	PR	02/01/2011	GW	123-20126	FEDERAL PLOVER 28-5 X	WK

General Comment:

Inspected Facilities

Facility ID: 258301 Type: WELL API Number: 123-20126 Status: PR Insp. Status: WK

Workover

Comment: MIT on 10/13/17

init: 530psi
 5 min: 516psi
 10 min: 511psi
 15 min: 507psi
 20 min: 504psi
 g/l: -26psi

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
All corrective actions noted in inspection doc#684904364 are still valid.	pesickac	10/13/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684904601	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4274293