

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401371976

Date Received:

08/10/2017

## FIR RESOLUTION FORM

### CA Summary:

11 of 11 CAs from the FIR responded to on this Form

11 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10359

Name of Operator: WARD PETROLEUM CORPORATION

Address: 215 WEST OAK STREET #1000

City: FORT COLLINS State: CO Zip: 80521

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Marshall hall

970 449 4634

marshall@wardpetroleumfc.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689300038

Inspection Date: 08/08/2017

FIR Submit Date: 08/08/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: WARD PETROLEUM CORPORATION

Company Number: 10359

Address: 215 WEST OAK STREET #1000

City: FORT COLLINS State: CO Zip: 80521

### LOCATION - Location ID: 311876

Location Name: LIND-611N66W Number: 24SWNW County: WELD

Qtrqr: SWN Sec: 24 Twp: 11N Range: 66W Meridian: 6  
W

Latitude: 40.909414 Longitude: -104.731203

### FACILITY - API Number: 05-123- -00 Facility ID: 251121

Facility Name: LIND Number: 24-1

Qtrqr: SWN Sec: 24 Twp: 11N Range: 66W Meridian: 6  
W

Latitude: 40.909414 Longitude: -104.731203

### CORRECTIVE ACTIONS:

1 ☒ CA# 90429

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 09/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator Comment: Animal burrow removed, fixed berm in spots

COGCC Decision: Approved

COGCC  
Representative:

2 ☒ CA# 90430

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 09/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Cleaned equipment, removed stained oil, performed maintenance on leaky valves and adjusted operating practice on various pieces of equipment to prevent small leaks.

COGCC Decision: Approved

COGCC  
Representative:

3 ☒ CA# 90431

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 09/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Cleaned equipment, removed stained oil, performed maintenance on leaky valves and adjusted operating practice on various pieces of equipment to prevent small leaks.

COGCC Decision: Approved

COGCC  
Representative:

4 ☒ CA# 90432

Corrective Action: 24 hours, remove free fluids, install wildlife protection device. Notify inspector when completed

Date: 08/09/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Inspector notified. Free fluids removed, net put over bucket.

COGCC Decision: Approved

COGCC  
Representative:

5 ☒ CA# 90433

Corrective Action: Comply with Rule 603.f .  
"10 days for weeds.  
10 days for trash.  
For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.  
30 days for unused equipment when machinery is not required to remove the equipment.  
90 days for unused equipment when machinery is required to remove the equipment."

Date: 09/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Riser was LOTO'd, inspector notified.

COGCC Decision: Approved

COGCC  
Representative:

6 ☒ CA# 90434

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e

Date: 08/18/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Soil replaced, engine cleaned up. Leaks mitigated

COGCC Decision: Approved

COGCC  
Representative:

7 ☒ CA# 90435

Corrective Action: Install sign to comply with Rule 210.d.

Date: 10/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Volumes stenciled

COGCC Decision: Approved

COGCC  
Representative:

8 ☒ CA# 90436

Corrective Action: Install sign to comply with Rule 210.d.

Date: 10/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Label attached.

COGCC Decision: Approved

COGCC  
Representative:

9 ☒ CA# 90437

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.  
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,  
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 09/08/2017

Response: CA COMPLETED

Date of Completion: 08/09/2017

Operator  
Comment: Equipment cleaned, re worked and inspected.

COGCC Decision: Approved

COGCC  
Representative:

**10** ☒ CA# 90438

Corrective Action: 24 hours. Remove free fluid, install wildlife protection. Notify inspector when completed Date: 08/09/2017

Response: CA COMPLETED Date of Completion: 08/09/2017

Operator Comment: Inspector notified. Netting installed on this drain bucket and others.

COGCC Decision: Approved

COGCC Representative:

**11** ☒ CA# 90439

Corrective Action: Comply with Rule 603.f . Date: 08/18/2017

Response: CA COMPLETED Date of Completion: 08/09/2017

Operator Comment: Weeds were sprayed prior to inspection. Weeds removed.

COGCC Decision: Approved

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Ward takes pride in how it operates its wells and will be changing several processes to ensure that such issues do not reoccur. Ward respectfully submits this FIR to assist in understanding the effort undertaken to address the inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marshall Hall

Signed: \_\_\_\_\_

Title: Petroleum Engineer

Date: 8/10/2017 10:33:31 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401371976	FIR RESOLUTION SUBMITTED
401371996	Image of drain bucket
401372000	Stenciled tank and sign
401372003	Image of repaired and cleaned valve

Total Attach: 4 Files